

Release Notes for DrayTek Vigor 120 v2 (UK/Ireland)

Firmware Version	3.2.8.2 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient Note: A previous firmware (3.2.8.1) was a critical release . This f/w includes all changes/improvements that were in 3.2.8.1.
Build Date	10 th April 2017
Release Date	24 th April 2017
Revision	63056
Applicable Models	Vigor 120 v2
ADSL Modem Code	332201 Annex A
Locale	UK & Ireland Only

New Features

(None)

Improvement

1. Resolved Web UI display issue

Known Issues

(None)

Important Note

This firmware is for the Vigor 120 v2. For the Vigor 120 v1 please see the website.

For more UK product details & specification, please visit <http://www.draytek.co.uk>

See <http://www.draytek.co.uk/support/product-knowledgebase> for Vigor 120 setup examples.

Different modem codes are available for the Vigor120 v2.

The standard UK modem code is 332201 and is included in the download zip.

Other modem codes can be downloaded from:

<http://www.draytek.com/ftp/Vigor120%20V2/Firmware/v3.2.8.2/annexA/>

Firmware File Types

The ZIP file contains the firmware with two different file extensions, .ALL and .RST. The firmware is identical but the RST file contains factory default settings. If you install the ALL file, your modem will retain all existing settings. If you use the RST file, all settings will be wiped from your modem.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the modem's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the modem's system maintenance menu and select the correct file. Ensure that you select the ALL file unless you want to wipe out your modem's settings back to factory default.



Manual Upgrade

If you cannot access the modem's menu, you can put the modem into 'TFTP' mode by holding the RESET whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the modem if there is a firmware/settings abnormality. Upgrading from the web interface is easier and recommended – this manual mode is only needed if the web interface is inaccessible.

Firmware Version	3.2.8.1 (Formal Release)
Release Type	Critical – Upgrade recommended immediately
Build Date	7 th February 2017
Release Date	31 st March 2017
Revision	62309
Applicable Models	Vigor 120 v2
ADSL Modem Code	332201 Annex A
Locale	UK & Ireland Only

New Features

(None)

Improvement

1. Security improvements including one or more considered critical.

Known Issues

1. Web UI menu has cosmetic display issue which will be corrected in the next firmware release

Firmware Version	3.2.8
Firmware Build	6th July 2015
Applicable Models	Vigor120 v2
ADSL Firmware	332201 Annex A
Locale	UK ONLY

New Features

1. Supports automatic reboot after a specified number of hours with the "sys autoreboot" telnet command

Improvement

(None)

Firmware Version	3.2.7
Firmware Build	6th February 2015
Applicable Models	Vigor120 v2
ADSL Firmware	332201 Annex A
Locale	UK ONLY

New Features

1. Support for ADSL Status reporting via WAN2 on routers that support it (currently Vigor 2860 3.7.8 & Vigor 2925 3.7.8.1).

Improvement

1. PPPoE server improvements for greater interoperability with more PPPoE clients

Firmware Version	3.2.6
Firmware Build	24th May 2011
Applicable Models	Vigor120 v2
ADSL Firmware	232201 Annex A
Locale	UK ONLY

New Features

(None)

Improvement

1. Minor region specific changes

Firmware Version	3.2.4.4
Firmware Build	27th July 2010
Applicable Models	Vigor120 v2
ADSL Firmware	232201 Annex A
Locale	UK ONLY

New Features

(None)

Improvement

1. Corrected: ADSL TX throughput can not exceed 1Mbps while ADSL link is on Annex M mode.
2. Improved: ADSL link problem.
3. Fixed PPPoE passthrough issue could cause some traffic not to be passed (ichat, 2nd life)

Firmware Version	3.2.4
Firmware Build	4th November 2009
Applicable Models	Vigor120 v2
ADSL Firmware	232201 Annex A
Locale	UK ONLY

New Features

(None)

Improvement

1. Improved: Some DSL interoperability problems occurred after updating DSL API driver.
2. Corrected: "G.Lite" item on WUI for annex A is lost.

First Firmware Release for this model

[END OF FILE]