

## Release Notes for DrayTek VigorSwitch P1085 (UK/Ireland)

Firmware Version	2.6.6 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	21 <sup>st</sup> October 2020
Release Date	12 <sup>th</sup> November 2020
Build Revision	1952
Applicable Models	VigorSwitch P1085
Locale	UK & Ireland Only

### New Features

(none)

### Improvements

1. The Switch's self-signed certificate will change upon upgrade for compatibility with new browser certificate requirements.  
Starting from September 2020, many client OS & browsers will limit publicly trusted TLS server certificate lifetime to 398 days or less, and connections will be rejected if certificates exceed this. This firmware patch will automatically re-sign all self-signed certificate lifetimes to 395 days (was 2 years or longer in older versions)
2. Support for statistics/counters information for each port on Status page
3. Support for editing the port number for HTTP management on [System Maintenance] > [Access Manager]

Firmware Version	2.6.4 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	16 <sup>th</sup> July 2020
Release Date	13 <sup>th</sup> August 2020
Build Revision	1909
Applicable Models	VigorSwitch P1085
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Loop Protection Per Port Settings added
2. [VLAN Management] > [Interface Settings] dashboard panel added
3. Improved compatibility between TR-069 and VigorACS

Firmware Version	2.6.0 (Formal Release)
Release Type	<b>First Firmware Release</b>
Build Date	2 <sup>nd</sup> February 2020
Release Date	15 <sup>th</sup> June 2020
Build Revision	1763
Applicable Models	VigorSwitch P1085
Locale	UK & Ireland Only

**First Firmware Release**

**[END OF FILE]**